



Photo of the Week



#597: The Worst

I've seen some crappy non-workstands in my time, but this one takes the cake, and I don't care if that machine was running or not. This reminds me of walking through a prop arc on a Navy flight deck – something not to be done under any circumstances.

Want more?
<< [Previous](#) | [Next](#) >>

www.public.navy.mil/comnavsafecen